




SIGNATURE  
**TECHNICAIR™**  
*Aircraft Maintenance*  
*A BBA Aviation company*

07/29/2024 N940MD MODEL:TBM 700 SN:1308 HM:579.5 WO#:S19-24-06835

1. Replaced ice detector P/N 0871CT2, S/N 2338 with inspected/tested ice detector P/N 0871CT2, S/N 2369. Ref. TBM 700 MM 30-80-00.
2. Replaced broken stair actuation cable with new P/N T700B526004310100. Ref. TBM 700 MM 52-60-00, 52-60-01.
3. Replaced landing gear controller P/N 6003777261, S/N 357 with inspected/tested landing gear controller P/N 6003777261, S/N 503. Ref. TBM 700 MM 32-60-01 and 07-10-00.

I certify that the aircraft, aircraft engine, propeller, or appliance identified above was repaired and or inspected in accordance with current FAA regulations and was found airworthy with respect to the work performed and is approved for return to service.

APPROVED BY



Signature TechnicAir Winston Salem NC FAA Repair Station PAIR208A