

HARTZELL

PROPELLER OWNER'S MANUAL



N200JN

HARTZELL

PROPELLER LOGBOOK

PROPELLER MODEL HC-I341R-IN

PROPELLER S/N NM67B

LOGBOOK # 1

PROP MODEL:
HC-13Y1R-1N
PROP S/N: NM67B
REG. NO: N200jn
WORK ORDER: 23084

Million Air - Salt Lake City

Repair Station No. K5SR339N
303 N 2370 W
Salt Lake City, Utah 84116
Phone: 801 359-2085

DATE: 1/27/2012
A/C TSN: 196.6
PROP TT: 196.6
HOBBS: 196.6


Prop Entries

PROPELLER HAS BEEN INSPECTED FOR A 100 HOUR INSPECTION PER FAR 43 APPENDIX D USING THE PIPER PA46-350P INSPECTION CHECKLIST 05-20-00 DATED SEPT 15, 2009 AS A REFERENCE, AND WAS DETERMINED TO BE IN AN AIRWORTHY CONDITION AND IS APPROVED FOR RETURN TO SERVICE FOR THE WORK PERFORMED AT THIS DATE AND TIME. *****PROPELLER 6 MONTH/ 12 MONTH LUBRICATION C/W.

I certify the airframe, engine and/or component identified herein was repaired and inspected in accordance with the current Million Air-SLC Repair Manual System and the Federal Aviation Regulations under which the operator is certified, and was determined to be in an Airworthy Condition at this date and time with regards to the inspection(s) and/or maintenance performed, and is approved for return to service as per those requirements. Pertinent details of the repair are on file under Work order No. 23084

DATE: 1/27/2012

SIGNED:


jray
Certified Repair Station No. K5SR339N

Work Order: 23084

Printed by EBis 3 (datcomedia.com)

Date	T	SUN AVIATION, INC., VERO BEACH, FL (VRB) Date: 10/29/12 Propeller Log N200JN Hobbs: 308.4 Model: HC-I3Y1R-1N Aircraft SN: 4636491 Prop. TT: 308.4 SN: NM67B		S.
		Accomplished an Annual Propeller Inspection IAW FAR 43, appendix "D" using the Piper PA46-350P 100 propeller Inspection report as a guide.		
		MAINTENANCE RELEASE: This aircraft, airframe, aircraft engine, propeller or appliance was repaired and inspected in accordance with current regulations of the Federal Aviation Administration and is approved for return to service. All work was performed in accordance with applicable aircraft, engine and or appliance maintenance manuals and instructions. Pertinent details are on file at the repair station office, W.O. # 29577 . AD's Researched THRU Rev. 2012.21		
		Signature  CRS # ECWR470D Sun Aviation, Inc. Municipal Airport, Vero Beach, FL 32961 (772) 562-9257		

SUN AVIATION, INC., Vero Beach, FL (VRB)

Date: 11/05/13

Hobbs: 401.7

PropTT: 401.7

Propeller Log

Model: HC-I3Y1R-1N

SN: NM67B

N200JN

Aircraft SN: 4636491

Performed an annual inspection, IAW FAR 43, appendix "D" using the Piper PA46-350P Inspection Report as a guide.

MAINTENANCE RELEASE: This aircraft, airframe, aircraft engine, propeller or appliance identified above was repaired and inspected in accordance with current regulations of the Federal Aviation Administration and is approved to return for service. All work was performed in accordance with applicable aircraft, engine and or appliance maintenance manuals and instructions. Pertinent details are on file at the repair station office, WO # S001252. A.D.'s researched through Rev. 2013.21

Signature


Sun Aviation, Inc, Municipal Airport, Vero Beach, FL 32961 (772) 562-9257

CRS# ECWR470D

NAPLES AIR CENTER, INC.

CRS X04R655M


230 AVIATION DRIVE SOUTH

NAPLES, FLORIDA 34104

AIRCRAFT: N263SP DATE: 10/30/14 WO: 12870 HOBBS: 479.5 TTSN: 479.5

PROPELLER LOG

THIS PROPELLER HAS BEEN INSPECTED IAW AN ANNUAL INSPECTION PER FAR 43 APPENDIX D, USING THE MANUFACTURER'S CHECKLIST AS A GUIDE, AND WAS FOUND TO BE IN AN AIRWORTHY CONDITION. ADS WERE CHECKED FOR COMPLIANCE THROUGH ISSUE 2014-20. L PERTINENT DETAILS OF THIS REPAIR ARE ON FILE AT THIS REPAIR STATION UNDER WORK ORDER 12870.


ROBERT L. HOUSE

FOR NAPLES AIR CENTER CRS X04R655M.

NAPLES AIR CENTER, INC.

CRS X04R655M

230 AVIATION DRIVE SOUTH

NAPLES, FLORIDA 34104

AIRCRAFT: N263SP DATE: 12/3/15 WO: 13139 HOBBS: 555.2 TTSN: 555.2

PROPELLER LOG

THIS PROPELLER HAS BEEN INSPECTED IAW AN ANNUAL INSPECTION PER FAR 43 APPENDIX D, USING THE MANUFACTURER'S CHECKLIST AS A GUIDE, AND WAS FOUND TO BE IN AN AIRWORTHY CONDITION. ADS WERE CHECKED FOR COMPLIANCE THROUGH ISSUE 2015-22. PERTINENT DETAILS OF THIS REPAIR ARE ON FILE AT THIS REPAIR STATION UNDER WORK ORDER 13139.


ROBERT L. HOUSE FOR NAPLES AIR CENTER CRS X04R655M.

SUN AVIATION, INC., Vero Beach, FL (VRB)

Date: 12/07/16

Hobbs: 619.9

PropTT: 619.9

Propeller Log

Model: HC-I3Y1R-1N

SN: NM67B

N263SP

Aircraft SN: 4636491

Performed an annual inspection, IAW FAR 43, appendix "D" using the Piper PA46-350P Inspection Report as a guide. Cleaned propeller deice slip ring per Piper PA46-350P MM 30-60-00. Removed engine baffle, removed prop deice brush block assembly and turned brushes and reinstalled per AMM 30-60-00.

MAINTENANCE RELEASE: This aircraft, airframe, aircraft engine, propeller or appliance identified above was repaired and inspected in accordance with current regulations of the Federal Aviation Administration and is approved to return for service. All work was performed in accordance with applicable aircraft, engine and or appliance maintenance manuals and instructions. Pertinent details are on file at the repair station office, WO # S002803. A.D.'s researched through Rev. 2016.23

Signature


Sun Aviation, Inc, Municipal Airport, Vero Beach, FL 32961 (772) 562-9257

CRS# ECWR470D

NAPLES AIR CENTER, INC.

CRS X04R655M


230 AVIATION DRIVE SOUTH

NAPLES, FLORIDA 34104

AIRCRAFT: N263SP DATE: 10/21/2017 WO: 13575 HM & TTIS 655.9

PROPELLER LOG

THIS PROPELLER INSPECTED IAW AN ANNUAL INSPECTION AS PER FAR 43 APP D USING MANUFACTURERS CHECKLIST AS A GUIDE, AND WAS DETERMINED TO BE IN AIRWORTHY CONDITION AT THIS TIME.


RODNEY G. CHASTAIN

FOR NAPLES AIR CENTER CRS X04R655M.

SUN AVIATION, INC., Vero Beach, FI (VRB)

Date: 10/01/18

Propeller Log

N263SP

Hobbs: 709.1

Model: HC-13Y1R-1N


Aircraft SN: 4636491

PropTT: 709.1

SN: NM67B

Performed an annual inspection, IAW FAR 43, appendix "D" using the Piper PA46-350P Inspection Report as a guide. Touched up paint on propeller per Hartzell owners manual 149, chapter 61-00-49. Cleaned propeller deice slip ring per Piper PA46-350P MM 30-60-00.

MAINTENANCE RELEASE: This aircraft, airframe, aircraft engine, propeller or appliance identified above was repaired and inspected in accordance with current regulations of the Federal Aviation Administration and is approved to return for service. All work was performed in accordance with applicable aircraft, engine and or appliance maintenance manuals and instructions. Pertinent details are on file at the repair station office, WO # S003647. A.D.'s researched through Rev. 2018.19

Signature 

Sun Aviation, Inc, Municipal Airport, Vero Beach, FL 32961 (772) 562-9257

CRS# ECWR470D

Propeller

A/C

Description of all operations pertaining to Airworthiness Directives,
Service Documents, etc.

SUN AVIATION, INC., Vero Beach, FL (VRB)

Date: 09/27/19

Propeller Log

N263SP

Hobbs: 752.0

Model: HC-13Y1R-1N

Aircraft SN: 4636491

PropTT: 752.0


SN: NM67B

Performed an annual inspection, IAW FAR 43, appendix "D" using the Piper PA46-350P

Inspection Report as a guide.

MAINTENANCE RELEASE: This aircraft, airframe, aircraft engine, propeller or appliance identified above was repaired and inspected in accordance with current regulations of the Federal Aviation Administration and is approved to return for service. All work was performed in accordance with applicable aircraft, engine and or appliance maintenance manuals and instructions. Pertinent details are on file at the repair station office, WO # S004027. A.D.'s researched through Rev. 2019.18

Signature



CRS# ECWR470D

Sun Aviation, Inc, Municipal Airport, Vero Beach, FL 32961 (772) 562-9257

SUN AVIATION, INC., Vero Beach, FI (VRB)

Date: 10/22/20

Propeller Log

N263SP

Hobbs: 757.0

Model: HC-I3Y1R-1N

Aircraft SN: 4636491

PropTT: 757.0

SN: NM67B

Performed an annual inspection, IAW FAR 43, appendix "D" using the Piper PA46-350P Inspection Report as a guide. Touched up paint on propeller per Hartzell owners manual 149 chapter 61-00-49. Cleaned propeller deice slip ring per MM 30-60-00.

MAINTENANCE RELEASE: This aircraft, airframe, aircraft engine, propeller or appliance identified above was repaired and inspected in accordance with current regulations of the Federal Aviation Administration and is approved to return for service. All work was performed in accordance with applicable aircraft, engine and or appliance maintenance manuals and instructions. Pertinent details are on file at the repair station office, WO # S004336. A.D.'s researched through Rev. 2020.21

Signature



CRS# ECWR470D

Sun Aviation, Inc, Municipal Airport, Vero Beach, FL 32961 (772) 562-9257

Date	Propeller	A/C	Description of all operations pertaining to Aircraft
	SUN AVIATION, INC., Vero Beach, FL (VRB)		
	Date: 11/05/21	Propeller Log	N263SP
	Hobbs: 765.3	Model: HC-13Y1R-1N	Aircraft SN: 4636491
	PropTT: 765.3	SN: NM67B	
	Performed an annual inspection, IAW FAR 43, appendix "D" using the Piper PA46-350P Inspection Report as a guide. Touched up paint on propeller per Hartzell owners manual 149 chapter 61-00-49.		
	MAINTENANCE RELEASE: This aircraft, airframe, aircraft engine, propeller or appliance identified above was repaired and inspected in accordance with current regulations of the Federal Aviation Administration and is approved to return for service. All work was performed in accordance with applicable aircraft, engine and or appliance maintenance manuals and instructions. Pertinent details are on file at the repair station office, WO # S004804 . A.D.'s researched through Rev. 2021.22		
	Signature 		CRS# ECWR470D
	Sun Aviation, Inc, Municipal Airport, Vero Beach, FL 32961 (772) 562-9257		

AIRCRAFT PROPELLER WORKS, INC
506 Charlotte Road, Auburndale, FL 33823 CRS# 4TZR125D

PROPELLER S/N NM67B WORK PERFORMED Overhauled
PROPELLER M/N HC-13Y1R-1N N7605+2

Propeller overhauled in accordance with Hartzell manuals 159, 202A, 113B and 135F. In compliance with SL-61-366 this propeller uses NYCO GN3058 grease, the use of any other grease during the maintenance of this propeller is prohibited. TTSN: Unknown TSO: 00.0

AD Compliance:

No AD's apply to this propeller at this time.

PERTINENT DETAILS ON FILE UNDER WORK ORDER: 5710P



Adam Flake

DATE: 11/14/2022

INSTALLER MUST CONFIRM ELIGIBILITY WITH APPLICABLE TECHNICAL DATA AND INSTALL I/A/W FAR 43.9

[illegible]