

SERVICE DE L'AÉRONEF - AIRCRAFT RECORD

Cachet - Signature réparateur
 Approbation pour remise en service
 Stamp and signature of overhauler
 Maintenance release

Détails vérifications et travaux entretien - Révisions partielles ou générales
 Modifications - Essais en vol
 Particulars of inspections and maintenance - Minor or major overhauls
 Modifications - Test flights

STATEMENT

SOCATA

Altimeter/Static and altitude reporting equipment systems have been tested and inspected per appendices E and F of part 43, as required by F.A.R. 91.411, Calibrated to 35000 Ft.

Signed

Dated 06/2010



DAHER-SOCATA

SOCATA

Agrément de Production
 FR - 21G - 0027

US STANDARD AIRWORTHINESS CERTIFICATE
 ISSUED ON JUL 01 2010
 INSTALLED IN AIRCRAFT ON BEHALF OF F.A.A.
 (A.E.U. 100) on JUL 01 2010

STATEMENT

SOCATA

Transponder has been tested and inspected and found to comply with appendix F of Part 43 in accordance with FAR 91.413

Signed

Dated 06/2010



Pierre Rouquet
 (GSAC Inspector)



JUL 01 2010

2

(LBID:7157)

For: FAA Approved Repair Station # X11R595Y

Date _____

SERVICE DE L'AÉRONEF - AIRCRAFT RECORD

Détails vérifications et travaux entretien - Révisions partielles ou générales
 Modifications - Essais en vol
 Particulars of inspections and maintenance - Minor or major overhauls
 Modifications - Test flights

Cachet - Signature réparateur
 Approbation pour remise en service
 Stamp and signature of overhauler
 Maintenance release

The New AVEX, Inc. C.R.S. X11R595Y

205 Durlay Avenue, Suite A, Camarillo, CA 93010 (805) 389-1188 FAX (805) 389-3323
 AIRFRAME Socata TBM 700 S/N: 552

Work Order: 8472

Tach: Hobbs: 73 TTSN: 73 Date: 8/20/2010 N850AV

1. Changed aircraft N# from N850AV to N850CA per FAA form 8050-64. New N# meets requirements of FAR 45.23 and 45.29.
2. Reconfigured GTX33 transponders #1 and #2 to reflect new Aircraft registration number N850CA I.A.W. Socata G1000 LMM 190-00871-00. Op checks good.

This aircraft, airframe, aircraft engine, propeller or appliance was repaired/inspected in accordance with the current Federal Aviation Regulations and has been found to be in an airworthy condition for scope of work performed. Pertinent details of the repair/inspection are on file at this Repair Station under Work Order No. 8472.

(LHD 7264)

Byron D. Sayer 8/20/10

Date
 For FAA Approved Repair Station # X11R595Y

SERVICE DE L'AÉRONEF - AIRCRAFT RECORD

4

Détails vérifications et travaux entretien - Révisions partielles ou générales

Modifications - Essais en vol

Particulars of inspections and maintenance - Minor or major overhauls

Modifications - Test flights

Cachet - Signature réparateur
Approbation pour remise en service
Stamp and signature of overhauler
Maintenance release

The New AVEX, Inc.

C.R.S. X1IR595Y

205 Durley Avenue, Suite A, Camarillo, CA 93010 (805) 389-1188 FAX (805) 389-3323

AIRFRAME

Socata TBM 700

Work Order: 8554

S/N: 552

N850CA

Tach:

Hobbs: 108.1

TTSN: 108.1

TLN: 72

Date: 10/15/2010

Page 1 of 3

1. Complied with First 100 Hour Inspection I.A.W. Socata MM Chapter 05-20-01, 05-20-02 and 05-20-05, a list of owner denied discrepancies provided to the aircraft owner. All AD's checked through Revision 2010-20; see AD compliance record provided with the aircraft logbook.
2. Complied with AD 2010-11-15, finding that the fire extinguisher with the S/N RM 71610, on board this airplane, had been reidentified as having acceptable content IAW Paragraph (f)(3) of the AD; no further action needed.
3. Complied with SB 70-118 paragraph C by the cleaning and lubrication of the left and right flap actuator rods I.A.W. Socata MM Chapter 12. Op checks good on the extension and retraction of the flaps.
4. Complied with the 100 hour/Annual servicing of the oxygen system I.A.W. Socata MM Chapter 12. Op and leak checks good.
5. Adjusted left and right aileron cable tensions and performed travel checks I.A.W. Socata mm Chapter 27. Op checks good.
6. Adjusted left and right spoiler cable tensions and performed travel checks I.A.W. Socata MM Chapter 27. Op checks good.
7. Adjusted elevator secondary stops and performed travel checks I.A.W. Socata MM Chapter 27. Op checks good.
8. Complied with verifying hardware torque on the inboard, center, and outboard section of the flaps and marked hardware with slippage marks I.A.W. Socata MM Chapter 60. Op checks good.
9. Inspected right wing fuel tank access panel #631 I.A.W. Socata MM Chapter 52. Leak checks good.
10. Inspected right wing fuel tank access panel #632 I.A.W. Socata MM Chapter 52. Leak checks good.
11. Adjusted new chute legs to left flap I.A.W. Socata MM Chapter 27. Op checks good on extension and retraction of flaps.
12. Performed new chute legs to right flap I.A.W. Socata MM Chapter 20. Op checks good on extension

[illegible]

SERVICE DE L'AÉRONEF - AIRCRAFT RECORD

Détails vérifications et travaux entretien - Révisions partielles ou générales

Modifications - Essais en vol

Particulars of inspections and maintenance - Minor or major overhauls

Modifications - Test flights

Cachet - Signature réparateur
Approbation pour remise en service
Stamp and signature of overhauler
Maintenance release

The New AVEX, Inc.

C.R.S. X1IR595Y

205 Durlay Avenue, Suite A, Camarillo, CA 93010 (805) 389-1188 FAX (805) 389-3323

AIRFRAME

Socata TBM 700

S/N: 552

N850CA

Work Order: 8554

Tach:

Hobbs: 108.1

TTSN: 108.1

TLN: 72

Date: 10/15/2010

This aircraft, airframe, aircraft engine, propeller or appliance was repaired/inspected in accordance with the current Federal Aviation Regulations and has been found to be in an airworthy condition for scope of work performed. Pertinent details of the repair/inspection are on file at this Repair Station under Work Order No. 8554.

(LBID:7367)

For: FAA Approved Repair Station # X1IR595Y

Byron D. Guy 10/15/10

Date

SERVICE DE L'AÉRONEF - AIRCRAFT RECORD

6

Détails vérifications et travaux entretien - Révisions partielles ou générales

Modifications - Essais en vol

Particulars of inspections and maintenance - Minor or major overhauls

Modifications - Test flights

Cachet - Signature réparateur
Approbation pour remise en service
Stamp and signature of overhauler
Maintenance release

The New AVEX, Inc.

C.R.S. X1IR595Y

205 Durley Avenue, Suite A, Camarillo, CA 93010 (805) 389-1188 FAX (805) 389-3323

AIRFRAME

Socata TBM 700

S/N: 552

N850CA

Work Order: 8631

Tach:

Hobbs: 124.6

TTSN: 124.6

Date: 12/10/2010

TLSN:

1. Complied with SB 70-188-21 by installation of opt kit 70 K122-00 I.A.W. Socata MM Chapter 21 and SB 70-188-21. Op checks good on ground test.

This aircraft, airframe, aircraft engine, propeller or appliance was repaired/inspected in accordance with the current Federal Aviation Regulations and has been found to be in an airworthy condition for scope of work performed. Pertinent details of the repair/inspection are on file at this Repair Station under Work Order No. 8631.

(LBID:7481)

For: FAA Approved Repair Station # X1IR595Y

Date

Byron D. Guey 12/10/10

SERVICE DE L'AÉRONAUTIQUE - AIRCRAFT RECORD

[illegible]