

SERVICE DE L'AÉRONEF - AIRCRAFT RECORD

23

Détails vérifications et travaux entretien - Révisions partielles ou générales

Modifications - Essais en vol

Particulars of inspections and maintenance - Minor or major overhauls

Modifications - Test flights

Cachet - Signature réparateur

Approbation pour remise en service

Stamp and signature of overhauler

Maintenance release

The New AVEX, Inc. C.R.S. X1IR595Y

205 Durley Avenue, Suite A, Camarillo, CA 93010 (805) 389-1188 FAX (805) 389-3323

AIRFRAME Socata TBM 700 S/N: 552 N850CA

Work Order: 11582 Date: 3/5/2015

Tach: Hobbs: 455.5 TTSN: 798.8 TLSN:

1. Complied with the annual servicing of the oxygen system I.A.W. Socata MM Chapter 35. Op and leak checks good.
2. Complied with the 3 month or 200 hour capacity check of the lead acid battery S/N 40599906 I.A.W. Concorde Battery Corp. S.T.C. SA00775LA instructions for continued airworthiness. Capacity checks good.

This aircraft, airframe, aircraft engine, propeller or appliance was repaired/inspected in accordance with the current Federal Aviation Regulations and has been found to be in an airworthy condition for scope of work performed. Pertinent details of the repair/inspection are on file at this Repair Station under Work Order No. 11582.

Byron D. Aug 3/5/15

Date

For: FAA Approved Repair Station # X1IR595Y

(LBID:11167)

...if de l'entretien
...enance moive

¿NECESITAS AYUDA?

IGRATISI Softwarey Planillas en every.c

- Utilize solamente productos Avery para resultados garantizados

Consejos Básicos de impresión, visita a ver

The New AVEX, Inc.

TEL: (805) 389-3323 FAX: (805) 389-3323

389-1166 FAX (805) 389-1166
C/N: 552
N850CA

Socata TBM 700
AIPERAME

Work Order: A11821

Hobbs: 531.8

1. Complied with the 24 month certification of airframe log book. See test results provided with the airframe log book. No defects

Combined with the 24 month certification of the transponder system I.A.W. F.A.V.S. for use at this time, you can rest assured that your investment will pay for itself.

Call today for more information or to schedule a demonstration. We'll show you how the Transponder System can save you money and increase your productivity.

Transponder Systems Inc., P.O. Box 108, St. Louis, MO 63108

Circle 17 on Reader Service Card

Z. Compared with the results found at this time. See test results provided with the software to v14.02 I.A.W. SB 70-215-

3. Complied with SB 70-215-34R1 by the upgrade of the static system IAW.

34R1. Up checks good.
Completed with RVSM 24 month inspection of the Air Data Computer and pitot-static system. RVSM manual. On checks good.

4. Complied with Socata MM Chapter 34 and owner operators approved by SOCATA, Inc. regarding visual and functional checks of the altitude alert

5. Complied with RVSM Manual annually recurring training. Complied with RVSM Manual Chapter 22-11-00 and owner operators approved RVSM Manual. No

system I.A.W. Socata MM defects noted at this time.

6 Complied with RVSM 12 month inspection of the autopilot and

Chapters 22 and 34. Up checks good.

7. Compiled with RV SW and RV SW and owner operators approved.

defects noted at this time.

8. Complied with RVSM annual recurrency

Complied with RVSM Manual annually recurring inspection/check of the manual.

Chapter 57-10-00, Page 601 and 602, Items 6 and 7.

No defects noted at time of inspection				
--	--	--	--	--

SERVICE DE L'AÉRONEF - AIRCRAFT RECORD

24

Détails vérifications et travaux entretien - Révisions partielles ou générales
Modifications - Essais en vol

Cachet - Signature réparateur

Particulars of inspections and maintenance - Minor or major overhauls

Approbation pour remise en service

Modifications - Test flights

Stamp and signature of overhauler

Maintenance release

The New AVEX, Inc.

C.R.S. X1IR595Y

Page 2 of 2

205 Durley Avenue, Suite A, Camarillo, CA 93010 (805) 389-1188 FAX (805) 389-3323

AIRFRAME

Socata TBM 700

S/N: 552

N850CA

Work Order: A11821

Tach:

Hobbs: 531.8

TTSN: 866.1

Date: 7/10/2015

TLSN: 677

This aircraft, airframe, aircraft engine, propeller or appliance was repaired/inspected in accordance with the current Federal Aviation Regulations and has been found to be in an airworthy condition for scope of work performed. Pertinent details of the repair/inspection are on file at this Repair Station under Work Order No. A11821.

(LBID:11453)

For: FAA Approved Repair Station # X1IR595Y

Date

Byron D. Sep - 7/10/15

SERVICE DE L'AÉRONEF - AIRCRAFT RECORD

25

Dates	Temps de vol depuis la précédente opération d'entretien Duration of flight since last maintenance operation	Heures totales Hours since manufacture	Heures depuis l'entretien majeur Hours since major maintenance	Nombre d'atterrissages Number of landings	Motif de l'entretien Maintenance motive
	<p>The New AVEX, Inc. C.R.S. X1R595Y Page 1 of 4</p> <p>205 Durley Avenue, Suite A, Camarillo, CA 93010 (805) 389-1188 FAX (805) 389-3323</p> <p>AIRFRAME Socata TBM 700 S/N: 552 N850CA</p> <p>Work Order: 11820 Tach: Hobbs: 531.8 TTSN: 866.1 Date: 7/13/2015 TLN: 677</p>				
	<p>1. Complied with a "B" inspection plus annual I.A.W. Socata MM Chapter 05-20-03 and 05-20-05. All AD's checked through revision 2015-12; see AD compliance record provided with the airframe logbook.</p>				
	<p>2. Complied with AD 2002-19-01 by testing the pilot and co-pilot control wheels to assure they don't become jammed I.A.W. SB 70-095-27R01. No defects found at this time.</p>				
	<p>3. Complied with AD 2015-08-07 by verifying that the inflatable harnesses installed on both crew masks, left S/N 141008 and right S/N 141005, were not affected IAW Zodiac SB MXH-35-240, Revision 7; no further action required.</p>				
	<p>4. Complied with SB 70-118-27R1 Paragraph C by the cleaning and lubrication of the left and right flap actuator rods I.A.W. Socata MM Chapter 27. Op checks good on the extension and retraction of the flaps.</p>				
	<p>5. Complied with Socata S/B 70-213-71 by removing the exhaust duct drain pipe and plugging ports to engine and EPA can in order to prevent clogging of the drain I.A.W. Socata S/B 70-213-71.</p>				
	<p>6. Complied with the 5 year weigh of the aircraft I.A.W. Socata MM Chapter 08. Updated weight and balance data installed in the aircraft POH.</p>				
	<p>7. Complied with the 3 year replacement of the shimmy damper Pure Silicone 100 cST hydraulic fluid I.A.W. Socata MM Chapter 32. Op and leak checks good on ground taxi.</p>				
	<p>8. Complied with the 400 hour or 2 year fuel quantity gage low level sensor test of the left wing I.A.W. Socata MM Chapter 28. No defects found at this time.</p>				
	<p>9. Complied with the 400 hour or 2 year fuel quantity gage low level sensor test of the right wing I.A.W. Socata MM Chapter 28. No defects found at this time.</p>				
	<p>10. Complied with the 24 month draining and filling of the refrigerant charge in the vapor cycle cooling system with new I.A.W. Socata MM Chapter 21. Op and leak checks good.</p>				
	<p>11. Complied with the 12 month certification of the ELT system I.A.W. FAR 91.207(d). No defects found</p>				

SERVICE DE L'AÉRONEF - AIRCRAFT RECORD

25

Détails vérifications et travaux entretien - Révisions partielles ou générales

Modifications - Essais en vol

Particulars of inspections and maintenance - Minor or major overhauls

Cachet - Signature réparateur

Approbation pour remise en service

Stamp and signature of overhauler

intenance release

The New AVEX, Inc. **C.R.S. X1IR595Y** **Page 2 of 4**

205 Durlay Avenue, Suite A, Camarillo, CA 93010 (805) 389-1188 FAX (805) 389-3323

AIRFRAME Socata TBM 700 S/N: 552 N850CA

Work Order: 11820 TTSN: 866.1 Date: 7/13/2015

Tach: Hobbs: 531.8 TLSN: 677

at this time. Battery next due replacement at 07/2019.

12. Performed 12 month B35, B36, B37 and B38 servo actuator clutch friction torque check I.A.W. Socata MM Chapter 22. Op checks good.

13. Complied with 1 year inspection of the left, right, and nose landing gears for condition, external and internal leaks in order for the landing gears to comply with the "Long Life Program" I.A.W. Socata MM Chapter 32; and lubricated landing gear axles I.A.W. Socata MM Chapter 12. No defects noted at this time. Op and leak checks good.

14. Complied with the annual servicing of the oxygen system I.A.W. Socata MM Chapter 35. Op and leak checks good.

15. Complied with the 3 month or 200 hour capacity check of the lead acid battery S/N 4059906 I.A.W. Concorde Battery Corp. S.T.C. SA00775LA instructions for continued airworthiness. Capacity checks good.

16. Reviewed Pilot's Operating Handbook and Supplements for revision currency with reference to Technical Publication Status issued online by Socata. Pilot's Operating Handbook and Supplements current at this time.

17. Adjusted fuel quantity indications for left and right wings I.A.W. Socata MM Chapter 28. Op checks good.

18. Removed cockpit evaporator P/N 1714A010001 S/N 130 and replaced with new P/N 1714A010001 S/N 252R I.A.W. Leibherr CMM Chapter 21. Op and leak checks good.

19. Removed nose tire P/N 071-311-0 S/N 9291W00351 and replaced with new P/N 071-311-0 S/N 4356S00147 I.A.W. Socata MM Chapter 32. Op and leak checks good.

20. Removed and replaced left main landing gear brake pressure and back plates with reconditioned units I.A.W. Socata MM Chapter 32. Op checks good.

21. Removed and replaced right main landing gear brake pressure and back plates with reconditioned

[illegible]

SERVICE DE L'AÉRONEF - AIRCRAFT RECORD

26

Détails vérifications et travaux entretien - Révisions partielles ou générales
Modifications - Essais en vol

Particulars of inspections and maintenance - Minor or major overhauls
Modifications - Test flights

Cachet - Signature réparateur
Approbation pour remise en service
Stamp and signature of overhauler
Maintenance release

[Handwritten signature: M. J. J. J.]

SERVICE DE L'AÉRONEF - AIRCRAFT RECORD

28

Détails vérifications et travaux entretien - Révisions partielles ou générales

Modifications - Essais en vol

Particulars of inspections and maintenance - Minor or major overhauls

Modifications - Test flights

Cachet - Signature réparateur

Approbation pour remise en service

Stamp and signature of overhauler

Maintenance release

The New AVEX, Inc.

C.R.S. X1IR595Y

205 Durley Avenue, Suite A, Camarillo, CA 93010 (805) 389-1188 FAX (805) 389-3323

AIRFRAME

Socata TBM 700

S/N: 552

N850CA

Work Order: 11820

Tach:

Hobbs: 531.8

TTSN: 866.1

TLN: 677

Date: 7/13/2015

This aircraft, airframe, aircraft engine, propeller or appliance was repaired/inspected in accordance with the current Federal Aviation Regulations and has been found to be in an airworthy condition for scope of work performed. Pertinent details of the repair/inspection are on file at this Repair Station under Work Order No. 11820.

(LBID:11454)

For: FAA Approved Repair Station # X1IR595Y

Byron D. Aug 7/13/15

Date

Page 4 of 4

SERVICE DE L'AÉRONEF - AIRCRAFT RECORD

29

Détails vérifications et travaux entretien - Révisions partielles ou générales
Modifications - Essais en vol

Cachet - Signature réparateur
Approbation pour remise en service
Stamp and signature of overhauler
Maintenance release

Particulars of inspections and maintenance - Minor or major overhauls
Modifications - Test flights

The New AVEX, Inc.

C.R.S. X1IR595Y

Page 2 of 4

205 Durley Avenue, Suite A, Camarillo, CA 93010 (805) 389-1188 FAX (805) 389-3323

AIRFRAME

Socata TBM 700

Work Order: 12579

S/N: 552

N850CA

Tach:

Hobbs: 1006.5

TTSN: 1006.5

TLSN: 751

Date: 8/1/2016

11. Complied with 600 hour check of the starter generator brushes I.A.W. Socata MM Chapter 24 and Thales SB 8012-24-004. Brushes found serviceable at this time.

12. Complied with a 600 hour check of the alternator brushes and replaced them with new I.A.W SIL-A-116 and Daher MM Chapter 24. Op checks good.

13. Complied with the 600 hour replacement of the fuel unit filter element with new I.A.W. Daher MM Chapter 28. Op and leak checks good.

14. Complied with the 24 month or 600 hour replacement of the air-conditioning compressor belt with new I.A.W. Daher MM Chapter 21. Op checks good.

15. Complied with the 24 month cleaning of the outflow and safety valve seats I.A.W. Daher MM Chapter 21. Op checks good.

16. Complied with the 12 month certification of the ELT system I.A.W. FAR 91.207(d). No defects found at this time. Battery next due replacement at 07/2019.

17. Performed 12 month B35, B36, B37 and B38 servo actuator clutch friction torque check I.A.W. Daher MM Chapter 22. Op checks good.

18. Complied with 1 year inspection of the left, right, and nose landing gears for condition, external and internal leaks in order for the landing gears to comply with the "Long Life Program" I.A.W. Daher MM Chapter 32; and lubricated landing gear axles I.A.W. Daher MM Chapter 12. No defects noted at this time. Op and leak checks good.

19. Complied with the annual servicing of the oxygen system I.A.W. Daher MM Chapter 35. Op and leak checks good.

20. Complied with the 3 month or 200 hour capacity check of the lead acid battery S/N 40599906 I.A.W. Concorde Battery Corp. S.I.C. SA00775LA instructions for continued airworthiness. Capacity checks good.

21. Reviewed Pilot's Operating Handbook and Supplements for revision currency with reference to

30

[illegible]

SERVICE DE L'AÉRONEF - AIRCRAFT RECORD

30

Détails vérifications et travaux entretien - Révisions partielles ou générales

Modifications - Essais en vol

Particulars of inspections and maintenance - Minor or major overhauls

Modifications - Test flights

Cachet - Signature réparateur

Approbation pour remise en service

Stamp and signature of overhauler

Maintenance release

The New AVEX, Inc.

C.R.S. X1IR595Y

205 Durlay Avenue, Suite A, Camarillo, CA 93010 (805) 389-1188 FAX (805) 389-3323

AIRFRAME

Socata TBM 700

S/N: 552

N850CA

Work Order: 12579

Tach:

Hobbs: 1006.5

TTSN: 1006.5

TLN: 751

Date: 8/1/2016

This aircraft, airframe, aircraft engine, propeller or appliance was repaired/inspected in accordance with the current Federal Aviation Regulations and has been found to be in an airworthy condition for scope of work performed. Pertinent details of the repair/inspection are on file at this Repair Station under Work Order No. 12579.

(LBID:12381)

For: FAA Approved Repair Station # X1IR595Y

Date

Beynon D. Dyer 8/1/16

Page 4 of 4

31

The New AVEX, Inc.		C.R.S. X1IR595Y		Page 1 of 2					
2205 Durley Avenue, Suite A, Camarillo, CA 93010 (805) 389-1188 FAX (805) 389-3323									
AIRFRAME		Socata TBM 700		N850CA					
Work Order: A12580		Hobbs: 1006.5		Date: 8/1/2016					
Tach:		TTSN: 1006.5		SN: 552					
				TLN: 751					
1.	Complied with SB 70-226-21 by A300 GAS controller software upgrade MOD 70-0454-21 of A300 controller P/N 82024A030401, S/N 82024-00231 and re-pinning of the A300 P4 connector I.A.W. Socata SB 70-226-21. Op checks good.								
2.	Complied with RVSM 12 month inspection of the autopilot altitude control system I.A.W. Daher MM Chapters 22 and 34 and owner operators approved RVSM manual. No defects noted at this time.								
3.	Complied with RVSM annual recurring inspection of the air data systems I.A.W. Daher MM Chapter 34-11-00-602 items 15, 16, 17, 18, 19, and 20 and owner operators approved RVSM manual. No defects noted at this time.								
4.	Complied with RVSM Manual annual recurring visual and functional checks of the altitude alerter system I.A.W. Daher MM Chapter 22-11-00 and owner operators approved RVSM manual. No defects noted at this time.								
5.	Complied with RVSM annual recurring fuselage inspection/check I.A.W. Daher MM Chapter 53-00-0-601 items 5, 6, 7, 8, 9, 10 and owner operators approved RVSM manual. No defects noted at this time.								
6.	Complied with RVSM Manual annually recurring inspection/check of the fairings I.A.W. Daher MM Chapter 57-10-00, Page 601 and 602, Items 6 and 7; and owner operators approved RVSM manual. No defects noted at this time.								
7.	Removed and replaced CWS pin at connector P141 with new I.A.W. Daher MM Chapter 22. Op checks good.								

SERVICE DE L'AÉRONEF - AIRCRAFT RECORD

31

Détails vérifications et travaux entretien - Révisions particulières ou générales

Modifications - Essais en vol

Particulars of inspections and maintenance - Minor or major overhauls

Modifications - Test flights

Cachet - Signature réparateur

Approbation pour remise en service

Stamp and signature of overhauler

Maintenance release

The New AVEX, Inc.

C.R.S. X1IR595Y

205 Durley Avenue, Suite A, Camarillo, CA 93010 (805) 389-1188 FAX (805) 389-3323

AIRFRAME

Socata TBM 700

Work Order: A12580

Tach:

Hobbs: 1006.5

TTSN: 1006.5

TLN: 751

N850CA

Date: 8/1/2016

This aircraft, airframe, aircraft engine, propeller or appliance was repaired/inspected in accordance with the current Federal Aviation Regulations and has been found to be in an airworthy condition for scope of work performed. Pertinent details of the repair/inspection are on file at this Repair Station under Work Order No. A12580.

(LBID:12376)

For: FAA Approved Repair Station # X1IR595Y

Date

Byron D. Dyer 8/1/16

Page 2 of 2

[illegible]

