



Exec Aero, LLC · 83 Nilson Way · Orlando, FL 32803 · 407-420-7934 · CRS#: EXAR968D

N940DF

Cycles: 603

COMPAGNIE DAHER, TBM 700, S/N: 1314

Hobbs: 999.5

April 01, 2025

1. Complied with 14CFR 91.409(a)(1) by performing an Annual Inspection IAW 14CFR 43.15(c)(1)(3).
2. C/W Daher standard Inspection Program A+ Inspection IAW 05-20-02 and 05-20-05.
3. Completed AD compliance research.
4. C/W AD 2025-01-04 (TE Flap Control System), Dated 3/11/2025, by Para (g)(1). Next due 4/2026 or 1400Hrs.
5. C/W AD 2025-02-08 (Emergency checklist update), Dated 03/19/2025, by Para (g),.
6. C/W SB 70-118-27-R3 (Inboard Flap Actuator) Para (C) 1Yr/400Hr Clean and lubricate the actuator screw.
7. C/W SB 70-337-76 (Pedestal Control Set Improvement) Installed P/N HA12-1280-901 - Harlow Hardware Kit.
8. C/W SL SL70-068-32 (Main Wheel Assembly P/N 40-489-Rupture Disc Torque).
9. C/W 1Yr Spoiler and aileron cable tension and safetying of turnbuckles check IAW 7-10-00.
10. C/W 1Yr Gaseous oxygen system for leaks, condition and attachment IAW 35-00-00.
11. C/W 1Yr Placards and markings inspection in areas 100, 200, 210, 300, 500, 600 and 700 IAW 11-21-00.
12. C/W 1Yr Lead-acid check capacity IAW 24-30-04. Capacity check 89.3%.
13. C/W 1Yr Passenger masks inspection and disinfect IAW 35-21-01.
14. C/W 1Yr Cockpit seats airbag systems - Check for wear and evidence of damage IAW 25-12-00.
15. C/W 1Yr Cockpit seats airbag systems - Do a functional test IAW 25-12-00.
16. C/W 1Yr Autothrottle do a functional test, Engine off IAW 22-30-00.
17. C/W 1Yr B35, B36 and B37 servo -actuators check cable condition and tension IAW 2-11-00.
18. C/W 1Yr B35,B36, and B37 servo actuators slip clutch manual override IAW 2-11-00.
19. C/W 1Yr Fire extinguisher weight and pressure check IAW 26-20-01.
20. C/W 1Yr Under floor drain inspection IAW 53-20-00.
21. C/W 1Yr Water separator filter check for condition and attachment IAW 30-10-04. Installed P/N 7423360051 - Water Separator Filter O-Ring (645001RR151) Rev/Lot: 0000398175, Installed P/N 7423360010 - O-Ring (645001RR010) Rev/Lot: 0000396340, Installed P/N 7423360015 - O-Ring (645001RR215) Rev/Lot: 0000379134, Installed P/N 7423060062 - Gasket (NAS1523C4E).
22. C/W 1Yr ELT operational test and record operating time IAW 25-61-00. C/W 14 CFR 91.207(d). ELT battery due: January 2026.
23. C/W 1Yr Rudder cable check tension and safetying of cables IAW 27-20-00.
24. C/W 1Yr Elevator trim tab control cables check tension and safetying of cables IAW 27-30-00.
25. C/W 1Yr Flap roller lubrication IAW 57-50-00.
26. C/W 1Yr Gaseous Oxygen Cylinder check for tightness, corrosion, distortion, attachment and hydro-static test date IAW 35-00-01.
27. C/W 1Yr Electro-mechanical generator filter cleanliness check IAW 32-35-01 Installed P/N 7423060406 - Hydraulic Screen O-Ring (MS28778-6) Rev/Lot: 9999913095.
28. C/W 1Yr L/H, R/H and Nose landing gear check for condition and leaks (Long Life) IAW 32-00-00.
29. C/W 1Yr L/H, R/H and Nose landing gear lubrication of landing gear axles IAW 32-00-00.
30. C/W 1Yr L/H and R/H check shock-absorber inflation pressure IAW 32-10-01.
31. C/W 1Yr Nose landing gear check shock absorber inflation pressure IAW 32-20-01.
32. C/W 1Yr Chip detectors do an operational test IAW 79-20-02. Installed (2) P/N 7423510012 - Pratt & Whitney Seal (AS3209-115).
33. C/W 1Yr/200Hr RVSM Static pressure ports check for condition and cleanliness IAW 31-11-00.
34. C/W 1Yr/200Hr RVSM External surfaces check IAW 53-00-00.
35. C/W 2Yr Altimetry check calibration IAW 34-11-00. Altimetry checks completed by Orlando Aircraft Services (CRS TP4R552M) WO#123068-1.
36. C/W 2Yr Outflow Valve-Clean valve seat IAW 21-30-02.
37. C/W 2Yr Safety Valve- Clean valve seat IAW 21-30-03.
38. C/W 5Yr Landing gear check for play and external Anti-corrosion protections. Check for internal anti corrosion protections (Long Life) IAW 32-10-01. Installed P/N 6028207283 - Bonding Strip.
39. C/W 5Yr Nose landing gear-do an oil change for the shock-absorber IAW 32-20-01 Installed (2) P/N 5757013240 - Lockwasher.
40. C/W 600Hr Stand by generator belt replacement IAW 24-30-05. Installed P/N 7133280007 - Hutchinson Belt (6PJ584).
41. C/W 800Hr Ice Detection System-Do an operational test #13 & #10 IAW 30-00-01.



Exec Aero, LLC · 83 Nilson Way · Orlando, FL 32803 · 407-420-7934 · CRS#: EXAR968D

- 42. Replaced lower torque link bushing and centering pin IAW 32-21-02. Installed P/N 7022262588 - Compass Axle 22588-000-01, Installed P/N 6052307223 - Bushing (22571-000-01).
- 43. Reseated right windshield heat controller connector IAW 30-40-00.
- 44. Operational and leak checks required.
- 45. Post inspection flight performed by Mike Sarsfield IAW 05-12-02.

With respect to the work performed, this airframe is approved for return to service. Details of work performed are on file with Exec Aero, LLC under work order: RS25-008.

Nathan Marler for CRS EXAR968D

A handwritten signature in blue ink, appearing to read 'Nathan Marler', written over a horizontal line.