



Exec Aero, LLC · 83 Nilson Way · Orlando, FL 32803 · 407-420-7934 · CRS#: EXAR968D

N940DF**Hartzell, HC-E5N-3C, S/N: RJ481****April 01, 2025**

Cycles: 603

Hobbs: 999.5

TTSN: 999.5

TTSO: 799.6

1. C/W 1Yr/400Hr Perform a Periodic Inspection of the propeller IAW Hartzell Manual 147 61-00-47.
2. C/W 1Yr Propeller lubrication IAW 61-10-01.
3. C/W 1Yr Propeller de-ice boot resistance check IAW Propeller Ice Protection Manual 180, 30-61-80.
4. C/W 1Yr Perform a detailed Inspection of non-rotating or airframe mounted components IAW 61-00-00.
5. C/W 1Yr/600Hr Beta ring and carbon block dimensional check IAW 61-10-00. Replaced beta carbon block. Installed P/N 6036387238 (Alt A-3026) - Carbon brush block.
6. C/W Propeller operational and leak checks.

I certify that this Propeller has been inspected in accordance with a Periodic Inspection and was determined to be in Airworthy condition.

With respect to the work performed, this propeller is approved for return to service. Details of work performed are on file with Exec Aero, LLC under work order: RS25-008.

Nathan Marler for CRS EXAR968D

A handwritten signature in blue ink, appearing to read 'Nathan Marler', is written over a horizontal line.