

N830MC
Hobbs: 2917.3

AC Time: 6430.2

Propeller S/N: FH513
June 01, 2023

Annual inspection performed per FAR part 43 App "D" and IAW with the Piper Navajo PA31-310 service manual checklist: Inspected and lubricated in accordance with annual inspection. All AD's checked through 12-2022.

I CERTIFY THAT THIS LEFT PROPELLER HAS BEEN INSPECTED IAW AN ANNUAL INSPECTION AND WAS FOUND TO BE IN AN AIRWORTHY CONDITION. PROPELLER RETURNED TO SERVICE.

Wayne Smith# 2289662



N830MC
Tach Time: 2851.3

AC Time: 6364.2

Propeller S/N: FH513
Mar 01, 2019

Annual inspection performed per FAR part 43 App "D" and IAW with the Piper Navajo PA31-310 service manual checklist: Inspected and lubricated in accordance with annual inspection. All AD's checked through 10-2019.

I CERTIFY THAT THIS LEFT PROPELLER HAS BEEN INSPECTED IAW AN ANNUAL INSPECTION AND WAS FOUND TO BE IN AN AIRWORTHY CONDITION. PROPELLER RETURNED TO SERVICE.

Wayne Smith IA# 2289662

Wayne Smith

N830MC
Tach Time: 2851.3

AC Time: 6364.2

Propeller S/N: FH513
Nov 01, 2020

Annual inspection performed per FAR part 43 App "D" and IAW with the Piper Navajo PA31-310 service manual checklist: Inspected and lubricated in accordance with annual inspection. All AD's checked through 22-2020.

I CERTIFY THAT THIS LEFT PROPELLER HAS BEEN INSPECTED IAW AN ANNUAL INSPECTION AND WAS FOUND TO BE IN AN AIRWORTHY CONDITION. PROPELLER RETURNED TO SERVICE.

Planewayne IA# 2289662

Wayne Smith

N830MC
Hobbs: 2860.0

AC Time: 6372.9

Propeller S/N: FH513
Nov 01, 2021

Annual inspection performed per FAR part 43 App "D" and IAW with the Piper Navajo PA31-310 service manual checklist: Inspected and lubricated in accordance with annual inspection. All AD's checked through 22-2021.

I CERTIFY THAT THIS LEFT PROPELLER HAS BEEN INSPECTED IAW AN ANNUAL INSPECTION AND WAS FOUND TO BE IN AN AIRWORTHY CONDITION. PROPELLER RETURNED TO SERVICE.

Wayne Smith# 2289662

Wayne Smith

N830MC
Tach Time: 2850.6

AC Time: 6364.2

Propeller S/N: FH513
Mar 01, 2016

Annual inspection performed per FAR part 43 App "D" and IAW with the Piper Navajo PA31-310 service manual checklist: Inspected and lubricated in accordance with annual inspection. All AD's checked through 07-2016.

I CERTIFY THAT THIS LEFT PROPELLER HAS BEEN INSPECTED IAW AN ANNUAL INSPECTION AND WAS FOUND TO BE IN AN AIRWORTHY CONDITION. PROPELLER RETURNED TO SERVICE.

Wayne Smith IA# 2289662

Wayne Smith

N830MC
Tach Time: 2850.6

AC Time: 6364.2

Propeller S/N: FH513
Mar 01, 2017

Annual inspection performed per FAR part 43 App "D" and IAW with the Piper Navajo PA31-310 service manual checklist: Inspected and lubricated in accordance with annual inspection. All AD's checked through 07-2017.

I CERTIFY THAT THIS LEFT PROPELLER HAS BEEN INSPECTED IAW AN ANNUAL INSPECTION AND WAS FOUND TO BE IN AN AIRWORTHY CONDITION. PROPELLER RETURNED TO SERVICE.

Wayne Smith IA# 2289662

Wayne Smith

N830MC
A/C Tach Time: 2851.3

AC Time: 6364.2

Propeller S/N: FH513
Mar 01, 2018

Annual inspection performed per FAR part 43 App "D" and IAW with the Piper Navajo PA31-310 service manual checklist: Inspected and lubricated in accordance with annual inspection. All AD's checked through 07-2018.

I CERTIFY THAT THIS LEFT PROPELLER HAS BEEN INSPECTED IAW AN ANNUAL INSPECTION AND WAS FOUND TO BE IN AN AIRWORTHY CONDITION. PROPELLER RETURNED TO SERVICE.

Wayne Smith IA# 2289662

Wayne Smith

A/C Tach 2849.9

Hub S/N FH513
Date 10-01-2011

Inspected and lubricated in accordance with annual inspection.

I CERTIFY THAT THIS LEFT PROPELLER HAS BEEN INSPECTED IAW AN ANNUAL INSPECTION AND WAS FOUND TO BE IN AN AIRWORTHY CONDITION. PROPELLER RETURNED TO SERVICE.

Robin Air LLC IA 2289662

A/C Tach 2850.5

A/C Time 6362.6

Hub S/N FH513
Date Oct 15, 2013

Inspected and lubricated in accordance with annual inspection.

I CERTIFY THAT THIS LEFT PROPELLER HAS BEEN INSPECTED IAW AN ANNUAL INSPECTION AND WAS FOUND TO BE IN AN AIRWORTHY CONDITION. PROPELLER RETURNED TO SERVICE.

Robin Air LLC IA 2289662

A/C Time 6364.2

Propeller S/N FH513
Jan 01, 2015

Inspected and lubricated in accordance with annual inspection.

I CERTIFY THAT THIS LEFT PROPELLER HAS BEEN INSPECTED IAW AN ANNUAL INSPECTION AND WAS FOUND TO BE IN AN AIRWORTHY CONDITION. PROPELLER RETURNED TO SERVICE.

Robin Air LLC IA# 2289662

Robin Air LLC IA# 2289662

A/C Tach 2850.5

A/C Time 6362.6

Hub S/N FH513
Date Oct 15, 2014

Inspected and lubricated in accordance with annual inspection.

I CERTIFY THAT THIS LEFT PROPELLER HAS BEEN INSPECTED IAW AN ANNUAL INSPECTION AND WAS FOUND TO BE IN AN AIRWORTHY CONDITION. PROPELLER RETURNED TO SERVICE.

Robin Air LLC IA 2289662

SUB-TOTALS this page

TOTALS—Carry forward to next page

SUB-TOTALS this page

TOTALS—Carry forward to next page