

N830MC
Hobbs: 2917.3


A/C Time: 6430.2

Propeller: S/N FH514
June 01, 2023

Annual inspection performed per FAR part 43 App "D" and IAW with the Piper Navajo PA31-310 service manual checklist: Inspected and lubricated in accordance with annual inspection. All AD checked through 12-2022.

I CERTIFY THAT THIS RIGHT PROPELLER HAS BEEN INSPECTED IAW AN ANNUAL INSPECTION AND WAS FOUND TO BE IN AN AIRWORTHY CONDITION. PROPELLER RETURNED TO SERVICE.

Wayne Smith IA# 2289662

A handwritten signature in black ink, appearing to read 'Wayne Smith', is written over a horizontal line.

N830MC
A/C Tach: 2851.3


A/C Time: 6364.2

Propeller: S/N FH514
May 01, 2019

Annual inspection performed per FAR part 43 App "D" and IAW with the Piper Navajo PA31-310 service manual checklist: Inspected and lubricated in accordance with annual inspection. All AD checked through 10-2019.

I CERTIFY THAT THIS RIGHT PROPELLER HAS BEEN INSPECTED IAW AN ANNUAL INSPECTION AND WAS FOUND TO BE IN AN AIRWORTHY CONDITION. PROPELLER RETURNED TO SERVICE.

Wayne Smith IA# 2289662



N830MC
A/C Tach: 2851.3


A/C Time: 6364.2

Propeller: S/N FH514
Nov 01, 2020

Annual inspection performed per FAR part 43 App "D" and IAW with the Piper Navajo PA31-310 service manual checklist: Inspected and lubricated in accordance with annual inspection. All AD checked through 22-2020.

I CERTIFY THAT THIS RIGHT PROPELLER HAS BEEN INSPECTED IAW AN ANNUAL INSPECTION AND WAS FOUND TO BE IN AN AIRWORTHY CONDITION. PROPELLER RETURNED TO SERVICE.

Planewayne IA# 2289662



N830MC
Hobbs: 2860.0


A/C Time: 6372.9

Propeller: S/N FH514
Nov 01, 2021

Annual inspection performed per FAR part 43 App "D" and IAW with the Piper Navajo PA31-310 service manual checklist: Inspected and lubricated in accordance with annual inspection. All AD checked through 22-2021.

I CERTIFY THAT THIS RIGHT PROPELLER HAS BEEN INSPECTED IAW AN ANNUAL INSPECTION AND WAS FOUND TO BE IN AN AIRWORTHY CONDITION. PROPELLER RETURNED TO SERVICE.

Wayne Smith IA# 2289662



N830MC
A/C Tach: 2850.6

A/C Time: 6364.2

Propeller: S/N FH514
Mar 01, 2016

Annual inspection performed per FAR part 43 App "D" and IAW with the Piper Navajo PA31-310 service manual checklist: Inspected and lubricated in accordance with annual inspection. All AD checked through 07-2016.

I CERTIFY THAT THIS RIGHT PROPELLER HAS BEEN INSPECTED IAW AN ANNUAL INSPECTION AND WAS FOUND TO BE IN AN AIRWORTHY CONDITION. PROPELLER RETURNED TO SERVICE.

Wayne Smith IA# 2289662



N830MC
A/C Tach: 2850.6


A/C Time: 6364.2

Propeller: S/N FH514
Mar 01, 2017

Annual inspection performed per FAR part 43 App "D" and IAW with the Piper Navajo PA31-310 service manual checklist: Inspected and lubricated in accordance with annual inspection. All AD checked through 07-2017.

I CERTIFY THAT THIS RIGHT PROPELLER HAS BEEN INSPECTED IAW AN ANNUAL INSPECTION AND WAS FOUND TO BE IN AN AIRWORTHY CONDITION. PROPELLER RETURNED TO SERVICE.

Wayne Smith IA# 2289662



N830MC
A/C Tach: 2851.3


A/C Time: 6364.2

Propeller: S/N FH514
May 01, 2018

Annual inspection performed per FAR part 43 App "D" and IAW with the Piper Navajo PA31-310 service manual checklist: Inspected and lubricated in accordance with annual inspection. All AD checked through 07-2018.

I CERTIFY THAT THIS RIGHT PROPELLER HAS BEEN INSPECTED IAW AN ANNUAL INSPECTION AND WAS FOUND TO BE IN AN AIRWORTHY CONDITION. PROPELLER RETURNED TO SERVICE.

Wayne Smith IA# 2289662



N830MC
A/C Tach 2849.9

A/C Time 6362.6

Propelled S/N FH514
Date 10-01-2011

Inspected and lubricated in accordance with annual inspection.

I CERTIFY THAT THIS RIGHT PROPELLER HAS BEEN INSPECTED IAW AN ANNUAL INSPECTION AND WAS FOUND TO BE IN AN AIRWORTHY CONDITION. PROPELLER RETURNED TO SERVICE.

Robin Air LLC IA# 2289662 Wayne Smith

N830MC
A/C Tach 2850.5

A/C Time 6362.6

Propelled S/N FH514
Date Oct 15, 2013

Inspected and lubricated in accordance with annual inspection.

I CERTIFY THAT THIS RIGHT PROPELLER HAS BEEN INSPECTED IAW AN ANNUAL INSPECTION AND WAS FOUND TO BE IN AN AIRWORTHY CONDITION. PROPELLER RETURNED TO SERVICE.

Robin Air LLC IA# 2289662 Wayne Smith

N830MC
A/C Tach 2850.5

A/C Time 6362.6

Propelled S/N FH514
Date Oct 15, 2014

Inspected and lubricated in accordance with annual inspection.

I CERTIFY THAT THIS RIGHT PROPELLER HAS BEEN INSPECTED IAW AN ANNUAL INSPECTION AND WAS FOUND TO BE IN AN AIRWORTHY CONDITION. PROPELLER RETURNED TO SERVICE.

Robin Air LLC IA# 2289662 Wayne Smith

N830MC
A/C Tach: 2850.6

A/C Time: 6364.2

Propelled: S/N FH514
Date: Jan 01, 2015

Inspected and lubricated in accordance with annual inspection.

I CERTIFY THAT THIS RIGHT PROPELLER HAS BEEN INSPECTED IAW AN ANNUAL INSPECTION AND WAS FOUND TO BE IN AN AIRWORTHY CONDITION. PROPELLER RETURNED TO SERVICE.

Robin Air LLC IA# 2289662 Wayne Smith