

Naples Air Center, Inc

230 Aviation Drive South.

Naples, FL 34104

Telephone: 239-643-1717 Ext. 219, Fax: 239-643-7794

Email: Maintenance@naples-air-center.com

Repair Station Certificate: XO4R655M

Shop Order: 13870

Acct Number: 2967

Opened: 3/15/2019**Closed: 6/20/2019**

Sold To: EDWIN B WALKER
2992 REGATTA RD.
NAPLES, FL 34103

Aircraft Number: ~~N263SP~~ **Type:** PA46-350P **S/N:** 4636491

Total Time:	727.0	Hobbs Time:	727.0	Tach Time:	LG Cycles:		
Eng#	Type	S/N	Time	Cycles	Prop Type	Prop S/N	Prop Time
1			727.0				727.0

Discrepancy: 1**Problem:**

REPLACE ALL CYLINDERS USING CUSTOMER SUPPLIED UNITS (FROM AN APPROVED SOURCE).

Action Taken:

REPLACED ALL CYLINDERS AS REQUIRED, PERFORMED FULL FUEL AND MONITORING SYSTEM SET UPS AND CHECKS, GROUND RUNS SATISFACTORY, NO LEAKS PRESENT.

Charges This Item:

Labor: \$ 7,200.00

Total For This Discrepancy: \$ 7,200.00

Discrepancy: 2**Problem:**

ADD CUSTOMER REQUESTED ENGINE COOLING BAFFLE REINFORCEMENTS.

FABRICATE AND INSTALL CUSTOMER REQUESTED REINFORCEMENTS TO ENGINE COOLING BAFFLES.

Action Taken:

FAB'D AND INSTALLED REINFORCEMENTS A/R.

Charges This Item:

Labor: \$ 450.00

Total For This Discrepancy: \$ 450.00

Discrepancy: 3**Problem:**

PERFORM FIRST OIL CHANGE AFTER TOP OVERHAUL, PERFORM METAL CHECKS AND RE-INSPECT ALL SYSTEMS.

Action Taken:

PERFORMED OIL CHANGE, NO METAL PRESENT IN OLD FILTER. INSPECTED ENTIRE ENGINE, NO PROBLEMS OR LEAKS PRESENT.

Charges This Item:

Labor: \$ 360.00

Total For This Discrepancy: \$ 360.00

Part Number	Description	Credit	Quantity	Units	Unit Price	Extended
111-4	HOSE		2.00	Each	14.800	\$ 29.60
4002-5S	STUD, S/S		4.00	Each	5.600	\$ 22.40
6504	CLAMP, MIN HOSE (7/32-5/8)		1.00	Each	0.180	\$ 0.18
6508	CLAMP MIN HOSE		1.00	Each	1.890	\$ 1.89
78084	GASKET		1.00	Each	141.380	\$ 141.38
951391	O-RING		12.00	Each	3.060	\$ 36.72
AA48103	TEMPEST OIL FILTER		2.00	Each	29.280	\$ 58.56
AN340-416	NUT		3.00	Each	0.140	\$ 0.42
AN526C832R6	SCREW		40.00	Each	0.070	\$ 2.80
AN960-10L	WASHER		6.00	Each	0.030	\$ 0.18

Naples Air Center, Inc

230 Aviation Drive South.

Naples, FL 34104

Telephone: 239-643-1717 Ext. 219, Fax: 239-643-7794

Email: Maintenance@naples-air-center.com

Repair Station Certificate: XO4R655M

AN960-516	WASHER, FLAT 5/16	4.00	Each	0.050	\$	0.20
AN960-8L	WASHER	40.00	Each	0.030	\$	1.20
MS21044N3	NUT	2.00	Each	0.140	\$	0.28
MS21045-08	NUT, FLEX NUT 8-32	40.00	Each	0.490	\$	19.60
MS21045L5	NUT	2.00		0.700	\$	1.40
MS35333-39	WASHER, LOCK, INTERNAL #10	5.00	Each	0.120	\$	0.60
MS35333-40	WASHER, LOCK, INTERNAL 1/4	48.00	Each	0.040	\$	1.92
MS35333-41	WASHER, LOCK, INTERNAL	13.00	Each	0.050	\$	0.65
MS35338-45	WASHER, LOCK, 5/16^	12.00	Each	0.060	\$	0.72
MS35489-17	GROMMET	1.00	Each	1.260	\$	1.26
MS35769-21	GASKET	1.00	Each	0.820	\$	0.82
OIL	AEROSHELL W100 - QT	26.00	QT	8.990	\$	233.74
RA77611	GASKET	1.00	Each	13.310	\$	13.31
S5073	COMPRESSOR	1.00	Each	0.000	\$	N/C
	S/N: 0934611880					
STD-2233	NUT	4.00	Each	16.320	\$	65.28
STD1410	NUT, EXHAUST	2.00	Each	2.390	\$	4.78

Miscellaneous Charges:

Misc Supplies: \$ 31.99

Summary:

Total Parts:	\$	639.89	Misc Supplies:	\$	31.99
Total Labor - 0.00 Hours:	\$	8,010.00			

Totals:

SubTotal:	\$	8,681.88
Total Charges:	\$	8,681.88
Amount Remaining:	\$	8,681.88

TERMS: PAYMENT UPON RECEIPT
THANK YOU FOR CHOOSING NAPLES AIR CENTER, INC.
FORM: NO. 3660

NAPLES AIR CENTER, INC.

CRS X04R655M


230 AVIATION DRIVE SOUTH

NAPLES, FLORIDA 34104

AIRCRAFT: N263SP DATE: 4/29/2019 WO: 13870 HM 727.0

ENGINE LOG

REPLACED ALL CYLINDERS USING CUSTOMER SUPPLIED UNITS (FROM AN APPROVED SOURCE) I/A/W
LYCOMING GUIDELINES. PERFORMED FULL FUEL AND MONITORING SYSTEM SET UPS AND CHECKS.
FABRICATED AND INSTALLED COOLING BAFFLE REINFORCEMENTS AS PER CUSTOMER REQUEST.
GROUND RUNS SATISFACTORY, NO LEAKS PRESENT.



RODNEY G. CHASTAIN

FOR NAPLES AIR CENTER CRS X04R655M.

NAPLES AIR CENTER, INC.

CRS X04R655M


230 AVIATION DRIVE SOUTH

NAPLES, FLORIDA 34104

AIRCRAFT: N263SP DATE: 6/20/2019 WO: 13870 HM 742.2

ENGINE LOG

PERFORMED FIRST OIL CHANGE AFTER TOP OVERHAUL. NO CONTAMINANTS PRESENT IN OLD FILTER.
INSPECTED ENTIRE ENGINE, NO ISSUES OR LEAKS PRESENT.



RODNEY G. CHASTAIN

FOR NAPLES AIR CENTER CRS X04R655M.

NAPLES AIR CENTER, INC. - RSM
X04R655M

PA 46-350P

Station: <u>RAF</u>	Date: <u>3/15/19</u>	'N' Number: <u>N263SP</u>	Serial No.: <u>4636491</u>
Tach: <u>—</u>	Hobbs: <u>7270</u>	Owners Name: <u>Sunny Walker</u>	W.O. <u>13870</u>
Hidden Damage Inspection required by FAR 145.211 (c)(ii)			YES ☐ NO ☒
Preliminary Inspection required by FAR 145.211 (c)(iii) complied with by			
Inspectors Name: <u>Rodney G. Chestain</u>		Discrepancies noted YES ☒ NO ☐	

Job Record form No. 8280

Entered By
and Date

Description of Discrepancy
and action taken

Mech. Insp.
and date

727.0

Discrepancy # <u>1</u>	<u>Replace all engine cylinders using customer supplied kits.</u>			
<u>Rev</u> <u>3/15/19</u>	P/N OFF:	P/N ON:	S/N OFF:	S/N ON: LABOR:
	<u>R+R engine cylinders (customer provided) IAW Lycoming T.O. 540 AE2A w/d cyl. Flange. Lycoming Model Service</u>			<u>CY</u> <u>4/29/19</u> <u>4/29/19</u>

Discrepancy # <u>2</u>	<u>Instruction No. 10290 pages 4-9 dated 12/13</u>			
<u>Rev</u> <u>4/19/19</u>	P/N OFF:	P/N ON:	S/N OFF:	S/N ON: LABOR:
	<u>Fabricate and install customer requested cooling baffle reinforcements.</u>			<u>CY</u> <u>4/29/19</u> <u>4/29/19</u>
	<u>Fabricated and installed reinforcements to engine cooling baffles a/r.</u>			

742.2

Discrepancy # <u>3</u>	<u>Aircraft due for oil change.</u>			
<u>Rev</u> <u>6/20/19</u>	P/N OFF:	P/N ON:	S/N OFF:	S/N ON: LABOR:
	<u>Drained oil, removed, cut open and inspected filter element, installed new AA48103-2 oil filter and added 11 quarts of W100 plus Aeroshell oil, leak checked oil filter.</u>			<u>JN</u> <u>6/20/19</u> <u>6/20/19</u>

THE AIRCRAFT, ENGINE, PROPELLER OR COMPONENT IDENTIFIED ABOVE WAS REPAIRED AND INSPECTED IN ACCORDANCE WITH CURRENT REGULATIONS OF THE FEDERAL AVIATION ADMINISTRATION AND IS APPROVED FOR RETURN TO SERVICE. PERTINENT DETAILS ARE ON FILE AT THIS REPAIR STATION.

INSPECTOR SIGNATURE: [Signature] DATE: 6/20/19 MAINTENANCE RELEASE ISSUED: ☒

N263 SP

DATE	MECHANIC	PART NUMBER	QTY	NOMENCLATURE	SERIAL #
4/11/19	Jordan	Q51391	12	Flt O-rings	
"	CY	16880, 111-4	2	Hvac (oil return)	
"	"	6504	1	Hvac Clamp	
4/12/19	CY	MS35333-39	5	Lock Washer	
4/12/19	Jason	6508	1	Clamp	
4/15/19	Jason	MS35333-40	24	Washer	
4/16/19	CY	MS35709-21	1	Crush Washer	
		AA48103-2	1	Filter	
		AA48103-2	1	Filter	
"	Jason	MS35338-45	12	Washer	
"	"	MS35333-41	7	Washer	
"	CY	MS35333-40	18	lock Washer	
"	CY	MS35489-17	1	Crommet	
4/17/19	Jason	MS35333-41	6	Washer	
"	CY	RA-77011	1	exhaust gasket	
"		MS21045LS	2	lock nut	
"	Jason	78084	1	gasket	
4/23	RC	STD-2233	4	lock NUTS	
"	"	STD-1410	2	NUTS.	
"	"	AN960-516	4		
"	CY	AN340-416	3	Nut	
"	"	MS35333-40	6	lock washer	
"	"	MS21044N3	2	lock Nut	
"	"	AN960-102	6	Washers	
4/24	Jordan	ACROSHILL W100	129K	Oil	
4/29/19	CY	W100	10K	oil	
5/15	Jason	~~1142012 8/MS405~~	54	Cambox	P/N 4002-55
5/21	AN960 CY	AN960-82	40	Washers	
"	"	AN526C832K6	40	Screws	
"	"	MS21045-08	40	Nuts	
4/24	CY	SB073	1	AC COMPRESSOR	
6/19/19	JN	AA48103-2	1	Filter (oil)	

Naples Air Center, Inc.
PARTS DEPARTMENT SIGNOUT SHEET

AIRCRAFT# N263SP WORK ORDER# 13870

DATE 3/15/19

N263SP

[illegible]